



FASEROPTIK


RFQ-Medizintechnik GmbH & Co. KG

E-Mail: info@rfq.de
<http://www.kaltlichtkabel.de>

Bruderhofstr. 10 - 12
D-78532 Tuttlingen

Telefax (07461) 9617-20
Telefon (07461) 9617-0

COMPARISON LIST FIBER LIGHT GUIDES



OLYMPUS W+I

SYSTEM STANDARD

Fibre Bundle Diameter	Length mm	RfQ-Article Cable	Projector Fitting	Endoscope Fitting	Olympus-Article
2,0	2300	on request	00-21116-63	00-21010-71	A3290
3,5	2300	00-21110-61	00-21116-63	00-21010-71	A3293
3,5 Kondensator	2300	not available	00-21116-63	00-21010-71	A3291
3,5 PDD	2300	not available	00-21116-63	00-21010-71	A3297
3,5 MRI	10000	not available	00-21116-63	00-21010-71	A8508
4,9	2300	00-21110-67	00-21116-63	00-21010-71	A3294
4,9	3000	00-21210-63	00-21116-63	00-21010-71	A3295
4,9 Kondensator	2300	not available	00-21116-63	00-21010-71	A3292
4,9 Kondensator	3000	not available	00-21116-63	00-21010-71	A3296
4,9 Typ CF	3000	not available	00-21116-63	00-21010-71	A3298
4,9 MRI	10000	not available	00-21116-63	00-21010-71	A8509
3,5	3000	00-21210-63	00-21116-63	00-21010-95	WA03200A
3,5 Kondensator	3000	not available	00-21116-63	00-21010-95	WA03202A
4,9	3000	00-21210-63	00-21116-63	00-21010-95	WA03210A
4,9 Kondensator	3000	not available	00-21116-63	00-21010-95	WA03212A

Fiber Light Guides are not 100% like Cables from Original Manufacturer
Errors excepted

LE=LIGHT INPUT
LA=LIGHT OUTPUT

FIBER LIGHT GUIDES FOR XENON LIGHT SOURCES PLEASE SEE PAGE 2



FASEROPTIK


RFQ-Medizintechnik GmbH & Co. KG

E-Mail: info@rfq.de
<http://www.kaltlichtkabel.de>

Bruderhofstr. 10 - 12
D-78532 Tuttlingen

Telefax (07461) 9617-20
Telefon (07461) 9617-0

COMPARISON LIST FIBER LIGHT GUIDES



OLYMPUS W+I

SYSTEM FUSED TO BE USED WITH HIGH TEMPERATURE LIGHT SOURCES

Fibre Bundle Diameter	Length mm	RfQ-Article Cable	Projector Fitting	Endoscope Fitting	Olympus-Article
2,0	2300	00-22430-40	00-21116-63	00-21010-71	A3290
3,5	2300	00-22330-40	00-21116-63	00-21010-71	A3293
3,5 Kondensator	2300	not available	00-21116-63	00-21010-71	A3291
3,5 PDD	2300	not available	00-21116-63	00-21010-71	A3297
3,5 MRI	10000	not available	00-21116-63	00-21010-71	A8508
4,9	2300	00-22230-40	00-21116-63	00-21010-71	A3294
4,9	3000	00-22230-50	00-21116-63	00-21010-71	A3295
4,9 Kondensator	2300	not available	00-21116-63	00-21010-71	A3292
4,9 Kondensator	3000	not available	00-21116-63	00-21010-71	A3296
4,9 Typ CF	3000	not available	00-21116-63	00-21010-71	A3298
4,9 MRI	10000	not available	00-21116-63	00-21010-71	A8509
3,5	3000	00-22330-50	00-21116-63	00-21010-95	WA03200A
3,5 Kondensator	3000	not available	00-21116-63	00-21010-95	WA03202A
4,9	3000	00-22230-50	00-21116-63	00-21010-95	WA03210A
4,9 Kondensator	3000	not available	00-21116-63	00-21010-95	WA03212A

Fiber Light Guides are not 100% like Cables from Original Manufacturer
Errors excepted

LE=LIGHT INPUT
LA=LIGHT OUTPUT